



AMD T580 Project to Set RPMC Operation Method v1.1

Step 1:

- a. Double-click "SET_RPMC.bat" in SET_RPMC package.



- b. When pop up follow information means RPMC set successfully.



Step 2:

- Manually restart the machine to complete the settings.